Power Center, Quezon Avenue cor. BIR Road, Diliman, Quezon City 1100
+632.8863.7100
TIPNGCP@ngcp.ph
www.ngcp.ph

Control No. NOSPI-CCMS-2026-013
August 20, 2026

MR. VON ERWIN G. AZAGRA
General Manager
Quezon II Electric Cooperative, Inc.
Infanta, Quezon

Subject: **NOTICE OF UNSCHEDULED POWER INTERRUPTION**

Dear Mr. Azagra,

Please be informed that we have encountered unplanned power service interruption affecting your franchise area, details are as follows:

Line Interrupted	Affected Area/s	Date/Day/Time	Reason
5LI1FAM-CMO Famy-Comon 69kV Line	Real, Infanta and General Nakar Quezon	August 19, 2026 (Wednesday) 1546H - 1609H	The outage is caused by the occurrence of whirlwind at the area of Brgy. Lewin, Lumban Laguna resulting to excessive conductor swinging. Similar incident is also noted at Brgy. Rizal, Pakil Laguna.

For your information and reference.

Sincerely,

FLAVIANO E. MASANGCAY, JR.
Sr. Manager, District 2, South Luzon Operations & Maintenance

Cc. **MS. MARIE FRANCES CARLOTA S. LIMON** – Special Assistant to the President, Office of the President
ATTY. CYNTHIA D. PEREZ-ALABANZA – AVP & Head, Public Affairs Department
MR. ARMAND S. DYSICO – AVP and Head, South Luzon Operations & Maintenance
MS. MARY JOYCE G. BALANCIO – Government Relations & Regional Affairs Department